

BOROUGH OF KEYPORT

UNIFIED PLANNING BOARD

DATE: 2/2/23

mu

TO: Denise Nellis, Board Secretary

FROM: Tony Vecchio, Fire Marshal

Re: 262 First St

() Fire hydrants are adequate in number and are in proper location; or

() Additional hydrants should be provided, as follows:

() Adequate water pressure and "fire flow" for this type project would be:

() Fire lanes/zones are adequate in number and proper locations; or

() Additional fire lanes/zones should be provided:

() In order to adequately review this project for fire safety, the following additional

Information is required: _____

* Co issued (1) comm (2) RES units
5/24/22